

December, 2010

To all customers:

Honma Golf Co., Ltd.

### **Complimentary exchange of defective “BERES MG700 1 star☆ Iron” golf club released in March 2010**

Honma Golf has found a defect on some of its BERES MG700 1 star grade Iron golf clubs, released in March 2010. The defect relates to the paint at the back of the club head peeling off, not caused by wear and tear nor scratches.

So far, following a set of nondestructive tests, the company has been unable to identify the cause of the defect and therefore are offering a complimentary exchange to all clients who purchased BERES MG700 1 star Iron clubs.

Following are more details:


#### **Product Model**

BERES MG700 1 star Iron (# 4 to 10, 11, AW, SW)

\* BERES MG700's 2 star • 3 star • 4 star • 5 star Irons series do not show mentioned problems.

#### **Defect Detail**

BERES MG700 1 star features a grey coating of paint on the cavity at the back of the club head. There seems to be a problem with the paint's adhesion strength, and there is a possibility that the coating may swell and peel off after use. This defect will not cause any bodily harm nor affect performance.



For inquiries, please contact our dealer where you purchased our product or the International Sales Division of Honma Golf Co., Ltd. Japan regarding exchanging your BERES MG700 1 star Iron golf club.

HONMA Golf Co., Ltd. (Japan)

E-mail: [inquiry@honmagolf.co.jp](mailto:inquiry@honmagolf.co.jp)

We are sorry for any inconvenience this may cause to our clients and we appreciate their cooperation and understanding on this.